

Super Multi 12,7 mm 8 x bandeja SATA carga interna grabadora de DVD drive para UJ210

DVD Writer Drive compatible con todos los formatos de DVD grabables y regrabables existentes es el más común para ordenadores de sobremesa y portátiles. También hay una unidad de DVD-ROM, unidad de BD-ROM, unidad combinada de disco Blu-Ray (BD-ROM/DVD ± RW/CD-RW), y disco Blu-ray Disc Writer.

Este DVD con el modelo no. UJ210 es un producto muy popular que cabe en la mayoría de los modelos de las marcas de fábrica usando 12.7 mm.

	E-sun Technology group Co.,Ltd	
Model	UJ210	
Type	Blu-ray DVDRW / Blu-ray DVD RW / Blu-ray Burner	
Interface	IDE (PATA)	
Thickness	12.7mm	
Load Type	Tray load	
Style	Internal	
Buffer size	2MB	
Specification	Size(L*W*H)	128*12.7*129mm
	Weight	300g
System requirement	Windows XP sp2 or sp3(update software is coming with the product),Win vista, Win 7, Mac OS8.6 or more high	
	Reading speed:	
	CD-ROM :Max 24X	
	DVD-ROM:Max 8X	
	BD-ROM: Max 6X	
	Writing speed:	
	CD-R :Max.24X	
	CD-RW :16X	
Working parameters	High Speed CD-RW :10X	
	Ultra Speed CD-RW :No Support	
	DVD-R :Max.8X	
	DVD-R DL :Max.4X	
	DVD-RW :Max.6X	
	DVD+R :Max.8X	
	DVD+R DL :Max.4X	
	DVD+RW :Max.8X	
	DVD-RAM :3X-5X P-CAV (4.7GB)	
	BD-R: 6x CAV(SL),4X P-CAV(DL)	
	BD-RE 2x CLV(SL),2X CLV(DL)	



Model No. UJ-210
Serial No. 6KAV03758 BAL-A
MARCH 2010
MANUFACTURED

CAUTION: RISK OF FIRE OR EXPLOSION
DO NOT DISPOSE OF THIS PRODUCT IN A FIRE
OR IN A WASTE BURNING PLANT.
DO NOT DISPOSE OF THIS PRODUCT IN A
WATER BODY OR IN A LANDFILL.
DO NOT DISPOSE OF THIS PRODUCT IN A
WATER BODY OR IN A LANDFILL.

CE mark
RoHS mark



MANUFACTURED: FEBRUARY 2008
SERIAL NO. 8BAHA001549 BFB-A



Model No. UJ-210
P/N CP218527-02

POWER SUPPLY: DC5V
COMPLIES WITH FDA RADIATION PERFORMANCE STANDARDS 21 CFR SUBCHAPTER J. 1301MP
Panasonic Communications Co., Ltd.
1-6-2, 4-Chome Minamimachi Hakata-Ku Fukuoka, Japan

CLASS 1 LASER PRODUCT
LASER CLASS 1

UL US CE EUC 30083
Made in Philippines J0G5030ZA



CAUTION: LASER BEAM FROM THIS DRIVE MAY BE REFLECTED FROM SURFACES AND CAUSE EYE HAZARD. DO NOT STARE INTO THE BEAM.
CAUTION: DO NOT OPEN THE DRIVE. NO USER ADJUSTMENT OR SERVICEABLE PARTS INSIDE.
DO NOT PUSH COVER.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.

DO NOT OPEN THE DRIVE.
NO USER ADJUSTMENT OR SERVICEABLE PARTS INSIDE.
DO NOT PUSH COVER.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.
REPAIRS: REPAIRS TO THIS DRIVE SHOULD BE PERFORMED BY QUALIFIED SERVICE PERSONNEL ONLY.