



**SERIAL
ATA**

Installation method

- 1.
- 2.
- 3.
- 4.

Made in China

 HDD


Fragile
Zerknirschung
切勿碰撞


Do not stop
the drive when running
Do not touch the
platters


Do not touch the
platters


Avoid contact with
platters
Prevent static contact
and shock


Read user's manual
for installation of system
components



304

HITACHI
www.hitachiget.com

CE MIC RoHS

D33373 HGS-HTSS42525K9A30 (B)

HDD: SK250-80
MODEL: HT542580K9A300
SV 700mA DC

5400RPM
SATA 3.0Gb/s

PRODUCT OF THAILAND TD
WARRANTY VOID IF ANY LABEL/ AUG-08
SCREW IS REMOVED OR BROKEN

P/N: 0A56151
M/N: 5000CCA52FDE333A
S/N: 080815886803WFJ4EHZF
MLC: DA2365 A141121

CT: *2ADRE01F3WF74Y*

HW/FW/PCB: A C3MP B/B

HPN: 454994-003

SPS-443918-001
R/C/D Date code: 050638


DO NOT COVER THIS HOLE →

FRAGILE

Don't shock / push cover

SERIAL ATA

Installation method



Made in China

HDD



